

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhnaur

Name of Road :- PMGSY Ankusi Chandrabauri to Chaupal + 1.

A. For Road


1. Damage Location Chainage :- 0 to 400 M, 400 to 800 M, 1200 to 1300 & 1550 M.
2. Damage Length :- 0.242 KM
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick's - Bat.
 - ii. Equipment's/Tools being used in Restoration works:- Tractor & JCB
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 0.242 KM, 92.175 m

B. For Bridge


1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-


Signature of JE/AE/EE


RR


Signature
(Name of Inspection)


Name of Work-
 Situation of Work-
 Agency by which work is executed-
 Date of Measurement-
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH- F.P.R.					
Name of work-	Most of the floor damaged				
	wood from PMGSSAMPUSI				
	change calculation to be made				
	under F.P.R.				
Agency-	Departmental				
Date of work-	8/5/2022				
(1) Providing and filling of					
batte midstone and					
damaged cement					
including cast of base					
batte and labour charge					
as per E/F					
CH-O-400m	1x	15.00x	3.50x	0.50	26.25M ³
	1x	30.00x	$\frac{4.50+5.20}{2}$	0.20	30.301
	1x	30.00x	$\frac{3.75+5.20}{2}$	0.20	27.1511
	1x	7.00x	2.50x	0.45	2.6251
	1x	8.00x	1.00x	0.20	1.601
" - 400-800m	1x	5.00x	1.00x	0.25	1.251
	1x	2.00x	1.00x	0.25	0.501
	1x	10.00x	1.00x	0.25	2.501
Continuation					92.175M ³

[illegible]

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
(1) providing and filling brick batte in ditcher and damaged embankment inclinations cost of brick batt and labour charge as per B/E Qty vide T.M.B.P - I(II) 92.175 m ³ @ 2004.26/m ³ L					184807 = 19
Add 1% C.S.T.				L	22176 = 86
Add 1% C.C.				L	1848 = 07
Add 10% S.F.				L	9512 = 46
				T.L	218344 = 58
				Sabla	218345 = 01
Prepared by 8/5/2022 AE  8/5/2022 A.E.					