

**Estimate for Restoration work of Road from L028 to Khangraitha Road for the year 2021-2022
in Bisfi Block**

Length-2.000 KM

Sr NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
	Nos	Length	Width	Height	Quantity	Unit	Rate	Amounts
0.97 0 km			(1.5+2.1)/2					
	1	30.00	1.80	0.600	32.400	m ³	18.00	
	1	2.50	2.00	0.300	1.500			
	L= 22.50 mtr.				33.900	Cum	1939.93	37829.00

Add 12% GST =Rs
Add 1% L/Cess =Rs
Add Signorage Fee(33.90x1032x10%) =Rs
total 19.50 =Rs

7892 4339 =
658 378 =
3498 2012 =
77811
70.12 - 44758 =

Bhendhy
29/11/21

RWD
Bisfi

Ammy
20/11/21

A E
RWD
Bisfi

27/11/21
27.11.21

EE
RWD
Benipatti

Damaged length = 22.50 mtr.

Qty = 19.50 m³.

verified and found correct

verified
28/11/21

27/11/21
27/11/21

W. ummy
27/11/2021
A3/Highman

Name of Rd: - 2028 to Khangra the.
Post facto T/S awarded for Rs. 44758.00
(Rs. Seventy four thousand seven hundred
fifty eight only.)

Reference letter no. 233 dated 21/2/22


Superintending Engineer
RWD Works Circle, Darranga
21/2/22

Report for Flood Damaged Work in the year 2021-22

Inspection :- 27.11.2021
+ 05.12.2021
Name of Block/PIU :- BBFC (Rural) WMD Dept. Nimes di Nishin Benipatti.
Name of Road :- Lo28 to Khangraitho.

For Road :-

1. Damage Location/ Chainage :- 302 At ch. 0.970 km.

2. Damage Length :- 32.50 Mtr.

3. Nature of Damage :- Due to heavy flood pot patch developed.

4. Details of Restoration Works :-

i. Material being used in Restoration Works :- Bricks, Batts.

ii. Equipment's/ Tools being used in Restoration Works :- Tractor & Roller.

iii. Procedure taken up in Restoration Works :- Section wise restoration works started/completed.

iv. Restored Length :- 32.50 Mtr.

Remarks :-

Works found satisfactory.

Signature of JE/AE

Signature of L.F.