

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- Harauli Main Road To Yadav Tol

A. For Road

1. Damage Location Chainage :- 30-90, 90-150
2. Damage Length :- 120.0 m
3. Nature of Damage :- Flood
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bats
 - ii. Equipment's/Tools being used in Restoration works:- Tractor
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 120.0 m 263-20m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

grade - 'S'

Signature of JE/AE/EE

Chandrupur
12/05/22

2036
244/22
RR

Signature
(Name of Inspection)

[Signature]

Hasauli main Road to Yadav Tol

Schedule XLV-Form No. 134

Jhaujharpur

DIVISION

Madhepur

SUB-DIVISION

3101

MEASUREMENT BOOK

[illegible]