

Estimate for Restoration work of Road from Patar to Andauli Road for the year 2021-2022 in Length-1.750 KM Madhawapur Block								
Sr NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amounts
800	1	30.00	4.05	0.20	24.30			
					24.30	Cum	1939.93	47140
Add 12% GST							=Rs	5657
Add 1% L/Cess							=Rs	471
Add Signorage Fee (365.55x1063x10%)							=Rs	2508
Tota							=Rs	55776

[Signature]
20-11-21
J E
R W D
Madhawapur

[Signature]
20/11/21
A E
R W D
Madhawapur

[Signature]
27-11-21
E E
R W D
Benipatti

check & verified

[Signature]
20.12.2021
S.E

[Signature]
20/12/2021
A E

[Signature]
20/12/21
E.E

Post factor T/S Accorded for Rs 55776.00 (Rs fifty five thousand seven hundred seventy six only.)
Reference Letter no. 233 dated 21/2/22
of E.E darbhanga

[Signature]
Superintending Engineer
RWD Works Circle, Darbhanga

29

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20.12.21 Name of PIU :- RWD (W) Div. Darbhanga-2

Name of Block :- MADHWAPUR (RWD(W) Div Benipatti)

Name of Road :- ANDAULT TO PATARGHAT PASHCHIM

For Road :-

1. Damage Location/ Chainage :- 0.800Km

2. Damage Length :- 30m

3. Nature of Damage :- Breach and pot holes due to flood

4. Details of Restoration Works :-


i. Material being used in Restoration Works : Brick Bats


ii. Equipment's/ Tools being used in Restoration Works Tractor & Roller

iii. Procedure taken up in Restoration Works Filling & Compaction

iv. Restored Length : 30m, Restored Quantity: 24.3m³

Remarks :- Work found Satisfactory


20.12.21
Signature of JE/AE


20/12/21
Signature of E.E