

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- PMGSY Road To Barham Mahadali Tol

A. For Road


1. Damage Location Chainage :- 600 - 700, 800 - 1000
2. Damage Length :- 85.0 m
3. Nature of Damage :- Flood
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bala
 - ii. Equipment's/Tools being used in Restoration works:- Tractor
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 85.0 - 70 m - 471.75m³


B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:- grade (S)
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-


Signature of JE/AE/EE


20/4/22
RR


Signature
(Name of Inspection)

Pmssy Road to Barsheem Mahadlit Tel

Schedule XLV-Form No. 134

Jhaujharpor

DIVISION

Madhepor

SUB-DIVISION

3104

MEASUREMENT BOOK

① Providing and Filling..

brick bats

1 X 30.00 m	X $\frac{3.50 + 5.50}{2}$	X 1.40 m	= 189.00 m ³
1 X 30.00 m	X $\frac{3.75 + 5.75}{2}$	X $\frac{6.40 + 1.60}{2}$	= 213.75 "
1 X 10.00 m	X $\frac{3.60 + 5.60}{2}$	X 1.50 m	= 69.00 "
		Qty.	471.75 m ³

17/5/22

AE

Scanned with CamScanner

[illegible]