

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhnau

Name of Road :- Muslim Tol To Kachuahat Kalisthan

A. For Road

1. Damage Location Chainage :- 100, 170, 200

2. Damage Length :- 27.0 m

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

Brick Bats

ii. Equipment's/Tools being used in Restoration works:-

Tractor, Back hoe loader

iii. Procedure taken up in Restoration works:- 24 m³

iv. Restored Length:- 27.0 m

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

RR
28/04/22

J.E

2036
24/4/22
EE

Signature
(Name of Inspection)

No. and date of agreement	Contents
(These four lines should be repeated at the commencement of the measurement relating to each work)	

Scanned with CamScanner

Scanned with CamScanner