

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhopur

Name of Road :- Yadav to 1 to Nima Mahadalit tola

A. For Road

1. Damage Location Chainage :- 50 to 200 m, 600 m
2. Damage Length :- 54.00 m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bat
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 54 m - 25.55 m²


B. For Bridge


1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

grad - 'S'


28/04/22
Signature of JE/AE/EE


20/4/22
RR


28/04/22
Signature
(Name of Inspection)

YADAV TOL TO ALMA MAHARAJA TOLA

Measurement Book

Schedule XLY-Form No. 134

JHANSHAPUR

DIVISION

MADHEPUR

SUB-DIVISION

2038

