

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

|                                                     |  |                      |
|-----------------------------------------------------|--|----------------------|
| Date of Inspection : 5/6/22                         |  | District: Aurangabad |
| Division : Daudnagar                                |  | Length (km): 1.45 KM |
| Name of the Road: Haspura Sansa Road to Tihul Bigha |  |                      |
| Scheme/Programme: PMGSY                             |  |                      |

| Sl. No.                                                                                                          | Parameters to be checked                                                                                              | Remarks (S/U) |
|------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|---------------|
| 1.                                                                                                               | <b>Pavement</b> BT / CC                                                                                               |               |
| a)                                                                                                               | Condition of Surfacing CC                                                                                             | U             |
| b)                                                                                                               | Riding Quality                                                                                                        | S             |
| c)                                                                                                               | Road Camber                                                                                                           | S             |
| d)                                                                                                               | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                          | U             |
| e)                                                                                                               | Contraction Joints provided or not (CC Pavement)                                                                      | S             |
| f)                                                                                                               | Compaction of flank/slope & raincuts if any                                                                           | S             |
| <b>Observation Remarks:-</b><br>BT Surface is in good condition & CC surface is Rough & exposed aggregate in CC. |                                                                                                                       |               |
| 2.                                                                                                               | <b>Cross Drainage</b>                                                                                                 |               |
| a)                                                                                                               | Condition of head walls in Hume pipe culverts including its painting                                                  | S             |
| b)                                                                                                               | Condition of Abutment & Wing walls, Slab in RCC culverts                                                              | N/A           |
| c)                                                                                                               | Condition of railings/slab/approach for Bridges                                                                       | N/A           |
| d)                                                                                                               | Condition of Vent Clearance                                                                                           | S             |
| <b>Observation Remarks:-</b><br>Hume pipe culvert is in good condition.                                          |                                                                                                                       |               |
| 3.                                                                                                               | <b>Road Furniture</b>                                                                                                 |               |
| a)                                                                                                               | Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained | S             |
| <b>Observation Remarks:-</b><br>Informatory & Maintenance board, km & 200m & Road signage is in lined in road.   |                                                                                                                       |               |
| 4.                                                                                                               | <b>Compliance History</b>                                                                                             |               |
| a)                                                                                                               | Status of ATR's & any others                                                                                          | -             |

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) U

Name of Officer:- Ratnesh Paswan  
 Designature:- EE

22/5/22  
 5-6-22  
 (Signature)  
 E.E

Regional Laboratory  
 Muzaffarpur

Agree  
 as per  
 EO, Muzaffarpur