INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date o	of Inspection: 7/6/22 District: Allonyaba	d
Divisio	on: Daugnaga Length (km): 1.6 km	Made a second
Schow	of the Road: Dindayal Rajbanshiz to Lo41 e/Programme: Grand	
	0//2/	T 3
Sl. No.	Tarameters to be enecked	Remarks (S/U
1.	Pavement CC	130
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	ے
c)	Contraction Joints provided or not (CC Pavement)	S
ŋ	Compaction of flank/slope & raincuts if any	2
2.	Cross Drainage	
		S
a) (Condition of head walls in Hume pipe culverts including its painting	
a) (Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts	NA
a) (b) (c) (Condition of head walls in Hume pipe culverts including its painting	
a) (b) (c) (Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance on Remarks:-	N/A N/A S
a) (c) (c) (d) (d) (d) (d) (d) (d) (d) (d) (d) (d	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance on Remarks:-	N/A N/A
a) (Co) (Co) (Co) (Co) (Co) (Co) (Co) (Co	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance on Remarks:- Hume pipe culvered is in g	N/A N/A S
Re W sto	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance on Remarks:- Hume pipe culvert is in g coad Furniture hether sign boards/informatory/cautionary Board/ km & 200m	N/A N/A S ood Condition
Re W sto	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance On Remarks:- Hume pipe culvered is in g made Furniture The their sign boards/informatory/cautionary Board/km & 200m ones/Pavement road markings are provided and maintained Remarks:- matory a maintenance board, km 4 200 m	N/A N/A S ood Condition

Overall Rating	tions, and		2000 to 1000
Overall Rating		Satisfactory (S)/ Unsatisfactory (U)	C
		Butistactory (5) Chantistactory (6)	

Rodnesh EE Paswan Name of Officer:-Designature:-

(Signature) 7:6-22

(Signature) 7:6-22

E-E

Regional laboratory

EO, Murger Myzaffar pur

EO, Murger