## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Distala	f Inspection: 7/6/22 District: AWLGING	
	Length (km): 8.6 KM	
Name	of the Road: Alison Jabag paina road - Amo	una
Schem	ie/Programme: New M	
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, expending aggregates in case of CC Pavement.	osed N/A N/A
e)	Contraction Joints provided or not (CC Pavement)	N/A
f)	Compaction of flank/slope & raincuts if any	S
To the		
		•
2.	Cross Drainage	
<b>2.</b> a)	Cross Drainage  Condition of head walls in Hume pipe culverts including its paint	ting 3
- Vige		ting S
a)	Condition of head walls in Hume pipe culverts including its paint	
a) b) c) d)	Condition of head walls in Hume pipe culverts including its paint Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	N/A
a) b) c) d)	Condition of head walls in Hume pipe culverts including its paint Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-	N/A N/A
a) b) c) d)	Condition of head walls in Hume pipe culverts including its paint Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-	N/A N/A S
a) b) c) d) Observa	Condition of head walls in Hume pipe culverts including its paint Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-  Hume pipe culvert is in	N/A N/A S good Condition.
a) b) c) d) Observa	Condition of head walls in Hume pipe culverts including its paint Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-  Hume pipe culvert is in  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 20 stones/Pavement road markings are provided and maintained ation Remarks:- connectory board, km & 200 m Stone 4 Road is	N/A N/A S S Sood Condition.
a) b) c) d) Observa  3. a) Observa	Condition of head walls in Hume pipe culverts including its paint Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-  Hume pipe culvert is in  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 20 stones/Pavement road markings are provided and maintained ation Remarks:-  pormatory board, km & 200 m Stone 4 Road is	N/A N/A S Sood Condition.  Om S Signage is timed
a) b) c) d) Observa  3. a) Observa  9nls in	Condition of head walls in Hume pipe culverts including its paint Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-  Hume pipe culvert is in  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 20 stones/Pavement road markings are provided and maintained ation Remarks:- commotory board, km & 200 m Stone 4 Road stones/Road. Maintenance board not available.	N/A N/A S Sood Condition.  Om S Signage is timed

Name of Officer: - Ratnesh Pasison

Designature:-

(Signature)
Regional luboratory
myserfarpor