## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 4 06 2022 District: ROHTAS					
Division: BIKRAMGUNJ Length (km): 2.50 Km					
Name of the Road: DURGADIH DERGAWAN TO INDRATH KALA					
	Programme: MMGSY				
Sl. No.	Parameters to be checked	Remarks (S/U)			
1.	Pavement	<b>13.</b>			
a)	Condition of Surfacing	S			
b)	Riding Quality	5			
c)	Road Camber	5			
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_			
e)	Contraction Joints provided or not (CC Pavement)	_			
f)	Compaction of flank/slope & raincuts if any	5			
Observa	tion Remarks:-				
2.	Cross Drainage				
<b>2.</b> a)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting	S			
		\$ -			
a)	Condition of head walls in Hume pipe culverts including its painting	\$ - -			
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	S - - - S			
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges	-			
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	-			
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	-			
a) b) c) d) Observa  3.	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance Ition Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	-			
a) b) c) d) Observa  3.	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance Ition Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m	- - S			
a) b) c) d) Observa  3.	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance Ition Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	- - S			
a) b) c) d) Observa	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance Ition Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained Ition Remarks:-	- - S			

Overall Rating	:	Satisfactory (S)/ Unsatisfactory (U)	SATISFACTORY
Name of Officer:- Designature:-	Sin EE	rant prased.	(Signature)

Vikash Kumar 4/06/2022