INSPECTION REPORT FOR ROUTINE MAINTENANCE

Divisio	n: Bhabhera Length (km): 3.200 km	
Name o	of the Road: Betari Muncleshwari path to Bau	wai Marhadal
Scheme	e/Programme:	
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
2.	Cross Drainage Condition of head walls in Hume pine culverts including its pointing	σ
2. a) b)	Condition of head walls in Hume pipe culverts including its painting	3
a)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts	<u> </u>
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	\$ - - S
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges	-
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-	-
a) b) c) d) Observa	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Gourd Sats factory	-
a) b) c) d) Observa 3.	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Found Satz factory Road Furniture Whether sign boards/informatory/cautionary Board/ km & 200m	- - S
a) b) c) d) Observa 3.	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Road Furniture Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	- - S
a) b) c) d) Observa	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Found Satto factory Road Furniture Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained ation Remarks:- Satto factory	- - S