## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 8/06/202	District: ROHTAS	
	Longth (KM): / SEC FO	n
Name of the Road: BIKRAMG	NJ NATWAR ROAD TO KHARA	IKPUR VIA KARMA
Scheme/Programme:		
	neters to be checked	Remarks (S/U)
1. Pavement		
a) Condition of Surfacing		S
b) Riding Quality		S
D 10 h		ζ
	ects such as visible cracks, exposed avement.	
e) Contraction Joints provide		
f) Compaction of flank/slope		_
Observation Remarks:-		
2. Cross Drainage		1.)
a) Condition of head walls in	Hume pipe culverts including its painting	V
a) Condition of head walls in	Hume pipe culverts including its painting Wing walls, Slab in RCC culverts	V
a) Condition of head walls in	Wing walls, Slab in RCC culverts	
<ul> <li>a) Condition of head walls in</li> <li>b) Condition of Abutment &amp;</li> <li>c) Condition of railings/slab/a</li> <li>d) Condition of Vent Clearan</li> </ul>	Wing walls, Slab in RCC culverts approach for Bridges ce	5
<ul> <li>a) Condition of head walls in</li> <li>b) Condition of Abutment &amp;</li> <li>c) Condition of railings/slab/a</li> <li>d) Condition of Vent Clearan</li> </ul>	Wing walls, Slab in RCC culverts approach for Bridges ce OF HP CULVERT PARAP	5
<ul> <li>a) Condition of head walls in</li> <li>b) Condition of Abutment &amp;</li> <li>c) Condition of railings/slab/s</li> <li>d) Condition of Vent Clearan</li> <li>Observation Remarks:- 2 NOS</li> </ul>	Wing walls, Slab in RCC culverts approach for Bridges ce OF HP CULVERT PARAP	5
a) Condition of head walls in b) Condition of Abutment & c) Condition of railings/slab/s d) Condition of Vent Clearan  Observation Remarks:- 2 NOS CRACI	Wing walls, Slab in RCC culverts approach for Bridges ce OF HP CULVERT PARAP	5
a) Condition of head walls in b) Condition of Abutment & c) Condition of railings/slab/s d) Condition of Vent Clearan  Observation Remarks:- 2 NOS CRACI	Wing walls, Slab in RCC culverts approach for Bridges ce OF HP CULVERT PARAP KED.	S ET WALL
a) Condition of head walls in b) Condition of Abutment & c) Condition of railings/slab/a d) Condition of Vent Clearan  Observation Remarks:- 2 NOS CRACI  3. Road Furniture  Whether sign boards/infostones/Pavement road man	Wing walls, Slab in RCC culverts approach for Bridges ce OF HP CULVERT PARAP KED.	S ET WALL
a) Condition of head walls in b) Condition of Abutment & c) Condition of railings/slab/s d) Condition of Vent Clearan  Observation Remarks:- 2 NOS CRACI  3. Road Furniture  a) Whether sign boards/infostones/Pavement road mar  Observation Remarks:-	Wing walls, Slab in RCC culverts approach for Bridges ce OF HP CULVERT PARAP KED.  rmatory/cautionary Board km & 200m kings are provided and maintained	S ET WALL
a) Condition of head walls in b) Condition of Abutment & c) Condition of railings/slab/s d) Condition of Vent Clearan  Observation Remarks:- 2 NOS CRAC  3. Road Furniture  a) Whether sign boards/info stones/Pavement road mar  Observation Remarks:-  4. Compliance History	Wing walls, Slab in RCC culverts approach for Bridges ce OF HP CULVERT PARAP KED.  rmatory/cautionary Board km & 200m kings are provided and maintained	S ET WALL

Name of Officer:- Sin Kart Praired.

Designature:- EE

Vikash ruman

8 | 6 | 2022

AE