



# ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

## DETAILED PROJECT REPORT FOR FDR

BIHAR



Name of the Road :-

pwd Dewariya road to chapra madho

DISTRICT	Muzaffarpur		
DIVISION	Muzaffarpur West		
BLOCK	Kanti		
TOTAL LENGTH OF ROAD	:	2.720	KM
CONSTRUCTION COST	:	<del>3.517</del> 3.422	Lac

Submitted By :-  
Executive Engineer  
RWD Work Division, Muzaffarpur West

## प्रतिवेदन

कार्य का नाम:- PWD Domains road to Chapra Madho  
.....पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में  
यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- Kanti  
वित्तीय वर्ष - 2021-22  
प्राक्कलित राशि - Rs.

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि Rs 3.422 lacs है, PWD Domains Road  
to Chapra Madho, प्रखण्ड- Kanti में यातायात बहाली हेतु आपातकालिन मरम्मत के  
लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13/11/2021 द्वारा  
दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू  
करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चालू अनुसूचित दर पर तैयार किया गया है। इसकी  
घटनोत्तर स्वीकृति अपेक्षित है। पत्रांक 4589 में है। M.S की धरि लेना -

Aramale  
05-11-2021

कनीय अभियंता

Boi  
05/11/2021

सहायक अभियंता

Kishor  
05/11/2021

कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल :-

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *EE RND Muz WCT*

2 Name of Block/Road :- *Konli*

(A) For Road:

1. Damage Location/Chainage :-
2. Damage Length :- *199m*
3. Nature of Damage :- *This road is damaged by heavy rain & flood*
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- *Brick's Pats - 144.20m<sup>2</sup> Rabbish - 68.255m<sup>2</sup>*
  - (ii) Equipment's/Tools being used in Restoration works:- *Roller, Tipper, Tractor etc*
  - (iii) Procedure taken up in Restoration works:
  - (iv) Restored Length :- *199m*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

*This road is found by satisfactory*

*N/A*

*Work found satisfactory*

*Normal*  
*05-11-2021*

Signature of JE/AE/EE

*[Signature]*

*12-12-21*

Signature

(Name of Inspection)

