




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT




Repair of Road MDR to Harshankarpur

STRICT	:-	Samastipur	
VISION	:-	Dalsingh Sarai	
OCK	:-	Dalsinghsarai	
TAL LENGTH OF ROAD	:-	0.168	KM
TAL COST OF PROJECT	:-	7.56	Lac

Site Photograph

me of Road:-MDR to Harishakarpur

Block-dalsinghsarai



Asinta

01/11/21
J.S.

SUMMARY OF COST ESTIMAT FOR THE PROJECT

NAME OF ROAD :- Repair of Road MDR to Harshankarpur

DISTRICT

SAMASTIPUR

BLOCK

Dalsinghsarai

S.NO	DESCRIPTION	AMOUNT LAKH
1	BRICK BAT	668946.000
	SUB TOTAL:-	668946.000
	12% GST on Total Amount:-	80273.520
	SUB TOTAL:-	6689.460
	Total Cost (including GST and Labour Cess	755909.000

Add 10% Senghar foot
Material cost
T.N. 2021

38548=00
Total - Rs 7,94,457=00

[Signature]
01/11/21
Junior Engineer

Assistant Engineer

[Signature]
1.12.21
Executive Engineer

D(W) Section, Dalsinghsarai

RWD (W) Sub Division, Dalsinghsarai

RWD, Works Division, Dalsinghsarai

Sanctioned Rs 7,94,500 = 00 only
Provisional estimate in company approved for Rs 7,94,500 = 00
Cash amount four thousand five hundred only
with an overdraft cheque 12, and 5.10%.

[Signature]
10/12/21
T.A

[Signature]
10.12.21
बसोबस बसिबस
शाहीब शाह दिवा
शाह बसब, बसबोडा

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST


LOCK

:- ALSINGHSARAI

DISTRICT :- SAMASTIPUR

NAME OF ROAD :- Repair of Road MDR to Harshankarpur

NO	ITEM OF WORK						AMOUNT	
A								
	TOTAL COST OF CONSTRUCTION					:-	Rs.	755909
					SUB TOTAL	:-	Rs.	755909


01/11/21


Junior Engineer

RWD (W) Section, Dalsinghsarai


11/11/21

Assistant Engineer

RWD (W) Sub Division,
Dalsinghsarai


01/11/21

Executive Engineer

RWD, Works Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghsarai

2. Name of Block – Dalsinghsarai

3. Name of Road/Bridge – MDR to Haosla Rasapur.

A. for Road

1. Damage Location/Chainage : 25.65540°N 85.834236°E
25.65548°N 85.833923°E

2. Damage Length : 0.168 Km

3. Nature of Damage : Due to heavy rain

4. Details of Restoration Works : Brick Bat

i. Material being used in Restoration works : Brick Bat

ii. Equipments/Tools being used in Restoration Works : Tractor, Roller

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.168 Km.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Alinta
05/04/22
J.H.

06/04/22
A.E.

05-04-2022
Executive Engineer,
R.W.D. Works Division,
Dalsinghsarai

05/04/22
Signature
(Name of Inspector)
E. B. Tish
R.D. Works Division