




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



L079 Panchyat Bhawan to Harijan Tola

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Mowa	
TOTAL LENGTH OF ROAD	:-	0.210	KM
TOTAL COST OF PROJECT	:-	6.23	Lac

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

CK :- Morwa

DISTRICT :- SAMASTIPUR

OF ROAD :- L079 Panchyat Bhawan to Harijan Tola

NO	ITEM OF WORK	AMOUNT
	TOTAL COST OF CONSTRUCTION	Rs. 623278
	SUB TOTAL	Rs. 623278

[Signature]
26/10/21
Junior Engineer

RWD (W) Section, Morwa

[Signature]
26/10/21
Assistant Engineer
RWD (W) Sub Division,
Morwa

[Signature]
01/12/21
Executive Engineer
RWD, Works Division,
Dalsinghsarai

*say 6,23,300 = 100 only
sanctioned for Rs 6,23,300 = 100 only
Land Twenty three Hums and Three Hums only
including one hand chase 125. CP 100, only*

[Signature]
10/12/21
b
40
10/12/21

[Signature]
10/12/21
T. A

SUMMARY OF COST ESTIMAT FOR THE PROJECT

ME OF ROAD :-L079 Panchyat Bhawan to Harijan Tola


RICT


SAMASTIPUR


CK

Morwa

NO	DESCRIPTION	AMOUNT LAKH
1	BAMBOO WORK	96358.2087
2	BRICK BATS	455215.320
	SUB TOTAL:-	551573.529
	12% GST on Total Amount:-	66188.823
	1% lab cess	5515.735
	Total Cost (including GST and Labour Cess	623278.087


26/10/21
Junior Engineer


26/10/21
Assistant Engineer


01.12.2021
Executive Engineer

Inspection Report for Flood Damage Work

Date: 05/4/22

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghsarai

2. Name of Block – Morwa

3. Name of Road/Bridge – L079 to Panchayat Bhawan Harigan Tola.

A. for Road

1. Damage Location/Chainage : 300m to 510m

2. Damage Length : 210m

3. Nature of Damage : Flood

4. Details of Restoration Works : Restoration work to be done.

i. Material being used in Restoration works : Bamboo & Bricks Bat, ~~Earthwork~~.

ii. Equipments/Tools being used in Restoration Works : Tractor, Labour, roller

iii. Procedure taken up in Restoration works : Bamboo piling with chachari and filling Bricks bats.

iv. Restored Length : 210m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

J.E.
05/4/22

A.E.
05/4/22

Executive Engineer,
R.W.D. Works Division,
Dalsinghsarai

W. M. Das Sarai
Factory
Signature
(Name of Inspector)
E. G. T. Sarai
W. M. Das Sarai