




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



T04 to Yadav Tola

STRICT	-	Samastipur	
VISION	-	Dalsingh Sarai	
LOCK	-	Mowa	
TOTAL LENGTH OF ROAD	-	0.102	KM
TOTAL COST OF PROJECT	-	2.28	Lac

Site Photograph

e of Road:-T04 to Yadav tola

Block-Morwa



Spind
2/11/21
J.E.

2/11/21
A2

SUMMARY OF COST ESTIMAT FOR THE PROJECT

NAME OF ROAD :- T04 to Yadav Tola

DISTRICT SAMASTIPUR

LOCK Morwa

S.NO	DESCRIPTION	AMOUNT LAKH
1	BAMBOO WORK	8806.698615
2	BRICK BATS	192567.544
	SUB TOTAL:-	201374.242
	12% GST on Total Amount:-	24164.909
	1% lab cess	2013.742
	Total Cost (including GST and Labour Cess)	227552.894

Say, 2, 27, 553 = 600

Handwritten signature
2/11/21
Junior Engineer

Handwritten signature
Assistant Engineer

Handwritten signature
01.12.21
Executive Engineer

Sanctioned
Provisionary Technical carry approved for Rs 2,27,553 = 600 say
Two Lakhs, Twenty seven thousand five hundred and fifty
three only including overhead chrg 12% CP 12%

Handwritten signature
10.12.21
वरीयय वरिष्ठ
वरीय वरिष्ठ विचार
वरी वरिष्ठ. वरिष्ठ
10/12/21
TA

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

DISTRICT :- SAMASTIPUR

BLOCK :- Morwa

NAME OF ROAD :- T04 to Yadav Tola

S.NO	ITEM OF WORK	AMOUNT
A		Rs. 227553
TOTAL COST OF CONSTRUCTION		
	SUB TOTAL	Rs. 227553

[Signature]
21/11/21
Junior Engineer

RWD (W) Section, Morwa

[Signature]
21/11/21
Assistant Engineer
RWD (W) Sub Division,
Morwa

[Signature]
01.12.21
Executive Engineer
RWD, Works Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date: 05/4/22

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghsarai

2. Name of Block – Morwa

3. Name of Road/Bridge – To 4 to Yadav Tola.

A. for Road

1. Damage Location/Chainage : 30m to 60m & 400m to 472m

2. Damage Length : 102m

3. Nature of Damage : Flood

4. Details of Restoration Works : Restoration to be done

i. Material being used in Restoration works : Bamboo, Brick bats ~~& Cement~~

ii. Equipments/Tools being used in Restoration Works : Tractor, Labour & rollers

iii. Procedure taken up in Restoration works : Bamboo piling with chachari and filling Brick bats.

iv. Restored Length : 102m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

[Signature]
J.E.
05/4/22

[Signature]
A.E.
05/4/22

Executive Engineer,
R.W.D. Works Division,
Dalsinghsarai

Wing done cat's
factory
[Signature]
Signature
(Name of Inspector)
E. G. Teym
Amr nms chm