

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Executive Engineer, R.W.D., Works, Division. Samastipur.

2. Name of Block - Kalyan Pura.

3. Name of Road/Bridge - TDS LADAUZA MIDDLE SCHOOL TO LAUDAURA
Pachim tola to UTARI TOLA.

A. for Road

1. Damage Location/Chainage : 100 m

2. Damage Length : 50 m

3. Nature of Damage : Pitch - 4.00 m

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks-bats, sand bag, Earth &

ii. Equipments/Tools being used in Restoration Works : Tractor, GCB ^{Bambo}

iii. Procedure taken up in Restoration works :

iv. Restored Length : 50 m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

19/4/22
J.E.

19/4/22
A.E.

25-4-22
Executive Engineer,
R.W.D. Works Division,
SAMASTIPUR.

Work done found
Satisfactory
Signature
25/4/22
Time of inspection
10:30 AM
19/4/22