

Inspection Report for flood Damage Work

Date :-

1- Name of PIUs :- R.W.D., (W) Division, Chapra - II

2- Name of Block/Road :- Banapur

LOG - Middle School Benhar to Gaudar bridge via
Ahar Tola

A. FOR RAOD

1- Damage Location/Chainage :- 2nd km (1.50 km to 1.90 km)

2- Damage Length :- 0.318 km

3- Nature of Damage :- Shoulder and Cent of Road due to flood

4- Details of Restoration :-

i- Material being used in Restoration

Prick bats

ii- Equipment/Tools being used in Restoration Works

Empty sand bag, brock

iii- Procedure taken up in Restoration Works

:- Manual.

iv- Restored Length

:- 0.318 km

B. FOR BRIDGE

1- Damage Location/Chainage :- 2nd km

2- Damage Length :- 0.318 km

3- Nature of Damage :- Shoulder and road Cent

4- Details of Restoration :- Brick bats fill in - in damage - Particular

i- Material being used in Restoration

Prick bats

ii- Equipment/Tools being used in Restoration Works

Manual

iii- Procedure taken up in Restoration Works

:- "

iv- Restored Length

0.318 km

Signature of JE/AE/EE

19.11.21

B. B.

Signature

(Name of Inspector)

Chapra