




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT





L043 to Keari

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Bibhutipur	
ESTIMATED LENGTH OF ROAD	:-	3.85	KM
ESTIMATED COST OF PROJECT	:-	11.45	Lac

Site Photograph

Location of Road:- L043 to Keri
 k- Bibhutipur

Dist- Samastipur



28/10/21
 26

28/10/21
 AE

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

BIBHUTIPUR

DISTRICT - SAMASTIPUR

OF ROAD :- 1043 to Kerali

NO	ITEM OF WORK	AMOUNT
	TOTAL COST OF CONSTRUCTION	Rs. 1144676
	SUB TOTAL	Rs. 1144676

[Signature]
28/10/21
Junior Engineer

RWD (W) Section, Bibhutipur

[Signature]
28/10/21
Assistant Engineer
RWD (W) Sub Division,
Bibhutipur

[Signature]
02.12.21
Executive Engineer
RWD, Works Division,
Dalsinghsaral

Sanctioned
Grand Techno Company *Approved* *for Rs 11,44,676 = 00 Say*
Eleven Lakh, forty four thousand and 300 + Hundred and 76
Sq only including D.H.C 12%, C.P 10% Buy

[Signature]
10/12/21

T. A.

[Signature]
10.12.21

बिबुतपुर कार्यलय
प्रमुख कार्य विभाग
मुख्य अभियंता, बिबुतपुर

[Signature]
10/12/21

SUMMARY OF COST ESTIMAT FOR THE PROJECT

ME OF ROAD :- L043 to Keri


RICT


SAMASTIPUR


K

BIBHUTIPUR

NO	DESCRIPTION	AMOUNT LAKH
1	BAMBOO WORK	115098.0958
2	BRICK BATS	700762.500
3	SAND FILLED BAGS	127147.320
4	GSB	69979.349
	SUB TOTAL:-	1012987.265
	12% GST on Total Amount:-	121558.472
	1% lab cess	10129.873
	Total Cost (including GST and Labour Cess)	1144675.609


28/10/21
Junior Engineer


28/10/21
Assistant Engineer


02-12-21
Executive Engineer

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division,

2. Name of Block – Bibhutipur

3. Name of Road/Bridge –

A. for Road

L 643 to Kerai

1. Damage Location/Chainage : 2.20 km – 2.405 km

2. Damage Length : 0.205 km

3. Nature of Damage : flood

4. Details of Restoration Works :

i. Material being used in Restoration works : Bamboo piling, Brick bats

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.205 km

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :


iii. Procedure taken up in Restoration works :

iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Dabhoi.


Signature
(Name of Inspector)
G. B. Tarmy
R.M. Ramsdun