

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :-

Madhepura

2 Name of Block :-

Murshiganj

3 Name of Road :-

paramahand pur Pachayut Ice ward no-10 Me P.M.C.S.Y Road
se Gnanesh Gupta Ghar fall

A. For Road

1 Damage Location/Chainage :-

2 Damage Length :-

0.053 km

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:- — Bridge bat, local sand.

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

A. K. M. A.

JE

Pringh
01/11/2021

AE

EE

Signature

(Name of inspector)

Schedule XLV-Form No. 134

Madhe pura

DIVISION

Murli Das

SUB-DIVISION

Paranandpur Panchayat ke ward no-10 me PMSY Roadse

Sanesh Gupta Chakraborty

Measurement Book

