

Estimate for Restoration work of Road from T03 to Damlaghat Road for the year 2021-2022 in

Length-1.865 KM

Bisfi Block

Sr NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amounts
0.00 to 0.050k m	1 ✓	14.00 ✓	3.10 3.0 ✓	0.3 ✓	13.020	12.6 M ³ ✓		
	1 ✓	18.70 ✓	3.10 3.0 ✓	0.45 0.3 ✓	26.087	16.83 M ³ ✓		
0.250k m	1 ✓	34.00 ✓	4.00 3.50 ✓	0.15 ✓	20.400	17.85 M ³ ✓		
	1 ✓	4.50 ✓	3.00 ✓	0.15 ✓	2.025			
					61.53	Cum ✓	1939.93	95735.00
								119367

L = 71.20 mtr. ✓

Add 12% GST

Add 1% Labour cess

Add Sigonara fee (61.53*1032.00*10%)

Total

47.28 M³

49.305 ✓

49.305

14324 11488 =

1194 957 =

6350 5088 =

141235

70 RS - 113268 =

Shandhy
JE
20-11-21

RWD
Bisfi

Amr
AE
20/11/21

RWD
Bisfi

Amr
EE
27.11.21

RWD
Benipatti

Damaged length = 71.20 mtr.

Restored Qty = 47.28 M³.
49.305 m³

Verified and found correct =

Amr
JE
27/11/21

Amr
27/11/2021
AE/Singharam

Amr
27/11/21


EE

Name of Road:- To3 to damlaghat
Road.

pwo me

Post-facto T/S awarded for Rs. 113268.00
(Rs. one lac thirteen thousand two hundred
sixty eight only.) of F.E. Darbhanga - 2
Reference Letter no. 233 dated 21/2/22

rdops


Superintending Engineer
RWD Works Circle, Darbhanga

. Ra

me

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 27-11-2021
 to 5.12.2022 Name of PIU :- RWD (W) Div. Darbhanga-2
 Suspected.

Name of Block/ PIU :- Bisfi (RWD(W) Div. Benipatti)

Name of Road :- "T03 To Damlaahet"

For Road :-

1. Damage Location/ Chainage :- (i) From ch. 0 to 0.050 km & (ii) At - 0.250 km.
2. Damage Length :- 71.20 meters.
3. Nature of Damage :- Due to heavy flood pot pitch developed.

4. Details of Restoration Works :-

- i. Material being used in Restoration Works :- Brick Bats.
- ii. Equipment's/ Tools being used in Restoration Works :- Tractor & Roller.
- iii. Procedure taken up in Restoration Works :- Section of mize work initiated / completed.
- iv. Restored Length :- 71.20 meters.

Remarks :- Work found satisfactory.

Signature of JE/AE

[Signature]
 19/10/2022
 JE

[Signature]
 Signature of E.E.