Continuation

1× 3.00× 1:00× 0.120 = 0.420

1x 300x 1.25 x0.11 = 6.53

1x

Sch.	XII	1_	Form	No	134
	71 6			140.	107

	orm No.		Contents of			
Particulars	Detai		l measure	THE RESERVE OF THE PERSON NAMED IN	area	
	No.	L.	B.	D.	1 100 A 10 7 23	
	1x	2.50 x	1.00 X	6.130	2 4-375	
	LX		1-00	10150	=0.750	
	12	3.00 X	150	X0-48	0 = 2.021	
	IX	4 ox	3-307	0750	=2180	
				=	18.68714	
	000		10		1200	
of.	739	=93	M	Ric	62572	
Addi	27.0	SCST		R.	4350 20	
Add	1%	Vce	95	B	3632	
	100000000000000000000000000000000000000	THE RESERVE OF THE PARTY OF THE	the second second	1032x	10%)192	
100 279				Z	40893	
			1	Rg	18,893	
•	21	1,			-	
Ç	There	they	2	1 1 1	-	
	11-	93				
		Pie	-	-	- in new	
799	1	18000	1919	19.33		
-						
ber-3	140	70 00	2 70	Was a	Constant?	
				1	Thomas	
Herry		1	2-21-2-3			
37272	01.0	233		1 - 1	39 32	
To the co	4	-			-	
		THE REAL PROPERTY.				

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection

:- 27.11.2021 to 05.12.2021

Name of PLU:-RWD (W) Div. Darbhanga-2

(Impeded).

Name of Block / PIU

:- Bisti (RWD(W) Div. Benipatti)

Name of Road

:- parohi to Khengraltha.

For Road

:- In between at 0:500 km to ch 1:00 km. :-1. Damage Location/ Chainage

2. Damage Length

3. Nature of Damage

:- 75.55 Mts. :- Due to heavy Hord pot patch developed

4. Details of Restoration Works

- Material being used in Restoration Works :- Brick らな。 i.
- Equipment's/ Tools being used in Restoration Works 1. Tractor & Roller's iî.
- Procedure taken up in Restoration Works !- Section wise restoration work initiated / completed. iii.
- Restored Length : 75-55 MY. iv.

Remarks:-

Signature of JE/AE Glorpor