

Estimate for Restoration work of Road from Bisfi Kokila Chaur to Narsam Road for the year 2021-2022 in Bisfi Block

Length-6.000 KM

NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
	Nos	Length	Width	Height	Quantity	Unit	Rate	Amounts
1.00 km	21	0.90	0.90	0.150	0.243	0.1215		
	1	9.00	1.75	0.225	3.544			
	21	0.60	0.60	0.150	0.108	0.054		
	1	1.50	3.00	0.150	0.675			
	1	1.00	1.00	0.150	0.150			
	21	1.50	1.50	0.150	1.013	0.3375		
2.00 km	1	5.00	1.50	0.150	1.125			
	1	6.70	1.60	0.150	1.608			
	1	17.00	2.50	0.225	0.20	0.563	8.5	
	1	6.80	2.00	0.150	2.040			
	1	6.50	2.75	2.5	0.225	4.022	3.65	
3.00 km	1	13.00	2.75	2.0	0.225	8.044	5.85	
	1	2.50	1.00	0.150	0.375			
	1	4.00	3.75	3.0	0.150	2.250	1.8	
	1	1.50	1.50	0.150	0.338			
	1	6.00	1.50	0.150	1.350			
4.00 km	1	7.50	1.00	0.150	1.125			
	1	8.00	1.00	0.150	1.200			
	99				38.771	Cum	1939.93	

65664.00

Add 12% GST
Add 1% L/Cess
Add Signorage Fee(3.771x1032x10%)
total

33.8485 m³ = Rs

9026 7680 =

752 657 =

4001 3493 =

88992
10. RS- 976942.00

[Signature]
JE
RWD
Bisfi

[Signature]
AE
RWD
Bisfi

[Signature]
EE
RWD
Benipatti

Damaged Length = 99 metre

Restored Qty = 33.8485 m³

Verified and found correct.

[Signature]
JE

[Signature]
27/11/2021
AE/Bisfi


[Signature]
27/11/21

Name of Road : - Bisfi Kokila Chowk
to Narcan Road.

Est. fact T/s accorded Rs. 77694.00
(Rs. Seventy seven thousand Six hundred
ninety four only.)

Reference Letter no. 233 dated 21/2/22


Superintending Engineer
RWD Works Circle, Darbhanga


21/2/22

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 27.11.2021 Name of PIU :- RWD (W) Div. Darbhanga-2
 to 05.12.2021 (Inspected).
 Name of Block/PIU :- Bizi (RWD works dept. (W) division Benipatti.
 Name of Road :- Bizi Koki chowk to Hussam.

For Road :-

1. Damage Location/ Chainage :- In Between ch. 1.00 KM to 4.00 KM.
2. Damage Length :- 99.00 mtr.
3. Nature of Damage :- Due to flood, pot patch developed.

4. Details of Restoration Works :-

- i. Material being used in Restoration Works :- Bridge Bats.
- ii. Equipment's/ Tools being used in Restoration Works :- Tractor, Roller.
- iii. Procedure taken up in Restoration Works :- Section wise restoration work initiated/completed.
- iv. Restored Length :- 99.00 mtr.

Remarks :- Work found satisfactory.

Signature of JE/AE

[Signature]
 19/10/2022
 JE

[Signature]
 19/10/2022
 Signature of E.E