

FD R

2021-22

193.Ho-63

Schedule XLV-Form No. 134

2013 to 2014

DIVISION

SUB-DIVISION

Block - Phamda

Measurement Book

Dhamdaha DIVISION

Dhamdaha SUB-DIVISION

50113 'to Hashi' talu

MEASUREMENT BOOK

No. - 63

ਪ੍ਰਮਾਣਿਤ ਰਿਸ਼ਾ ਗਾਨਾ ਦੇ ਤਿੰਨ ਰੁਜ਼ਮਾਨ
ਪੁਸ਼ਾ ਚ ਚੁਕਾਇਆ 1 ਮ 50 ਫੁਟ 8 ਇੰਚ
ਮਾਨੀ ਪੁਸ਼ਾ ਅਨੁਸਾਰ ਪ੍ਰਮਾਣਿਤ 46/1 ਫੁਟ
ਦਿਸਤਰ 5 ਮ 11 ਫੁਟ 1 ਇੰਚ 1 ਫੁਟ 11 ਇੰਚ

Name of Officer

Date of first entry **Executive Engineer**
Rural Works Department

Date of last entry **Works Division, Dhamdaha (Purnea)**

05/10/21

1

(These four lines should be repeated at the commencement of the measurements relating to one work.)

[illegible]

2/2	Providing and Laying			
	R.C.C Pipe N ^o 3			
	1000 mm CMM)			
	2 x 2250 x 2.50 m = 10 mite			
3/4	Labour for driving			
	62 mm to 75 mm			
	dia Bamboo Piles			
	Length - 34.70 m			
	4.0 m			
	- 8.40 m			
	- 3.85 m			
	Total 50.95 mite			
	50.95 x 4.11			
	0.3			2680 m

Continuation

Sch. XIV—Form No. 134

Particulars	Details of actual measurement				Contents of man
	No.	I.	II.	III.	
NAME OF WORK	F.D.				
(Movable) Restoration of					
Soil To Nakh Tola.					
Agency					
(ABSTRACT OF COST)					
1/1 Construction of					
embankment with					
Approved material					
76.812 Qty vide					
P.O. item No. (61)					
@ 171.203 / M ³					
					1131352

2/2 Providing and laying					
R.C.C. Pipe 11/2					
1000 (mm) Qty					
10 meter P.O.					
item No. (62) @ 11					
43.62 = 15/meter					
					11436212

3/3 Providing Brick					
bat including					
spreading and laying					
compacting 147.512					
Qty vide P.O. (65)					
@ 2188.35 / M ³					
					11322759

Continuation 113795152

By: 372, 315,

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4-1 A. Lab. dm for driving (62 mm to 75 mm) 680 mite dy vide on P. 01. (53) @ 52064/mite B. 35795					
5/5 supply, fitting & fixing of Bamboo 152.85 mite dy vide on P-02 - (05) @ 30212/mite B. 46042- B. 4,19,9142- Add G.S.T 12% - (11) 50,3902					

Add L.T. Laboratory (+)	41,992.00
Add S. Fee (+)	2500.20
Total	4,80,803.20
b. 4,80,803.20	
<u>Kumar</u>	<u>23-12-2022</u>
<u>(J.K.)</u>	<u>23/12/2021</u>
	A.P.
	(3)
	2-12-21

Continuation

Date: 04.12.21 Inspection Report for flood damage work (year 2021-22)
1. Name of PUs: Dhamdaha
2. Name of Block/Road: Dhamdaha-50113 to Nashi Tola

A. For Road

1. Damage Location/Chainage: - CH-2400 MTR.
2. Damage Length: - 36.5 MTR.
3. Nature of Damage: - Due to flood.
4. Details of Restoration:
 - i. Material being used in Restoration: - Bamboo, Brick bats
 - ii. Equipment/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works: - 36.5 MTR.
 - iv. Restored Length:

B. For Bridge

1. Damage Location/Chainage:
2. Damage Length:
3. Nature of Damage:
4. Details of Restoration:
 - i. Material being used in Restoration:
 - ii. Equipment/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length:

Signature of JE/AE/EE
04.12.2021

04.12.21
Executive Engineer,
Rural Works Department
Works Division Dhamdaha (Purnea)

Signature
04.12.21
(Name of Executive Engineer
(Rural Works) Division
PURNIA)

Scanned with CamScanner