

Dhamdaha

DIVISION

Rupauli

SUB-DIVISION

Milik Tola To SHGS

MEASUREMENT BOOK

No. 57

प्रमाणित किया जाता है कि इस मापी
पुस्तक में 1 क्विंटल वन्ने भरित है। यह
मापी पुस्तक अवर पुमंडूल पुहादिनी
रूपौली के नाम निहित किया जाता
है।

Name of Officer

Date of first entry

Date of last entry

Executive Engineer

Rural Works Department
Works Division, Dhamdaha (Purnea)

10/10/17

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/201K- for to milk tola tola					
Authority- B.F.R.W.D works					
Division Dhamdaha.					
① providing long and spreading gates but in ditches with the same do-do - Comp tub.					
(Avg width)					
$20 \times (0.65 + 0.75 + 1.70 + 1.30 + 1.50)$					

(Avg. Depth)					
$\times (0.60 + 1.20 + 1.55 + 1.70 + 2.45)$					
$20 \times 1.180 (Avg) \times 1.50 (Avg) = 35.40 m$					
(Avg width)					
$90 \times (0.65 + 0.75 + 1.75 + 1.25 + 1.50)$					
(Avg depth)					
$\times (0.65 + 1.20 + 1.50 + 1.70 + 2.45)$					
$30 \times 1.18 (Avg) \times 1.50 (Avg) = 53.10 m$					
(Avg width					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
N/Work - Const for to Dililatastok-6					
Authority - C.E.R. & O. works					
Division Dhamdaha					
① providing and Laying bricks					
bats in Litchest masonry					
company has bats with summer					
enriched cost of supply bats					
do do comp cost					
141.60 m ³ P- ①					
@ 2158.25/m ³					Rs 307870.00
add 12% L.S.T					Rs 37184.00
add 1% L.C.S					Rs 3079.00
add 10% S fee					Rs 18368.00
					Rs 3,68,521.00
18/12/2021					
J.E.					
12.12.21					

Continuation

Date:

Inspection Report for flood damage work

year
FDR (2021-22)

1. Name of PIUs-

Dhamdaha

2. Name of Block/Road-

Rupauli/milik to Lato SH-65

A. For Road

1. Damage Location/Chainage :

2. Damage Length

3. Nature of Damage

4. Details of Restoration

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

: Broken baffle

: Trolley, manual

: - manual

: 80 M (2, 68, 52) = 100

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length

3. Nature of Damage

4. Details of Restoration

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works: