

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division. SamastiPUR.

2. Name of Block – Kalyan PUR.

3. Name of Road/Bridge – TOS LA DAURA MIDDLE SCHOOL TO LA DAURA
A. for Road Pachim tola to UTARI TOLA.

1. Damage Location/Chainage : 100 m

2. Damage Length : 50 m

3. Nature of Damage : Ditch - 4.00 m

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks-buts, sand bag, Earth &

ii. Equipments/Tools being used in Restoration Works : Tractor, CCB
Bambo

iii. Procedure taken up in Restoration works :

iv. Restored Length : 50 m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

19/4/22
J.E.

19/4/22
A.E.

25.4.22
Executive Engineer,
R.W.D. Works Division,
SAMASTIPUR.

25/4/22
Signature
(Name of Inspector)
Sub Division Engineer