

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- Chamundo More to Addah Musalman Tol.

A. For Road

1. Damage Location Chainage :- 0.300 to 1100 M.
2. Damage Length :- ~~63.50M~~ 40.00m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick's Bat
 - ii. Equipment's/Tools being used in Restoration works:- Tractor & JCB.
 - iii. Procedure taken up in Restoration works:- 13-46 cm
 - iv. Restored Length:- ~~63.50M~~ 40m


B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE


23/4/22
RR


23/04/22
JE

— S —

Signature
(Name of Inspection)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
① providing and filling brick bats in ditches damaged embeankment - - - - -					
13.46 m ³ 8 V.T.M. D.P. - ①					
@ Rs. 2004.96/m ³					Rs. 26986.76
					Rs. 26986.76
Add 12% V.T.S.T. (+)					Rs. 3238.41
Add 1% Leases (+)					Rs. 269.87
Add 5% Free 10% (+)					1389.07
					1430.80
					31884.11
					Rs. 31925.84

say Rs. - 31926.00
31884.00

[Signature]
7/5/2022
AK

[Signature]
07/05/2022
SR

Continuation

EHAMUNDA MORE TO ADITDDH MUSALMAN TOL

Measurement Book

Schedule XLV-Form No. 134

JHANTHARPUR

DIVISION

MADHEPUR

SUB-DIVISION

2049