

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- Main Road to Wakali tal

A. For Road

1. Damage Location Chainage(km):- 0.120, 0.150, 0.160, 0.180

2. Damage Length :- 26.6 Mtr

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:- Brick Bat

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:- 26.6 Mtr

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

As per Attached Photo

grade 'S'

Chandana
20/04/22

Signature of JE/AE/EE

3-36
20/4/22
RR

2
3/14

Signature
(Name of Inspection)

Schedule XLV-Form No. 134
Main Road to Wakali Tal

Thanjharabur

DIVISION



Madhebur

SUB-DIVISION

2089

MEASUREMENT BOOK

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
(1) Providing and filling brick bats					
34.74 m ³ @ 11.74 MRP (1)					
Rs 2004.96/m ³ —				Rs.	69652.31
				Rs.	69652.31
Add 12% GST (P)				Rs.	8358.28
Add 1% L.C.S.S (P)				Rs.	696.52
Add 10% S. fee				Rs.	3585.17
					Rs. 81292.28
				Say Rs.	81292.00
 7/5/2020 A.G.					 02/05/2020 J.E.