

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- *Madhopur*

Name of Road :- *Balhti - Joga*

A. For Road

1. Damage Location Chainage :-
2. Damage Length :- *80.50 m*
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- *Brick Bats*
 - ii. Equipment's/Tools being used in Restoration works:- *99.63 m*
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

— S —

[Signature]
29/04/22

Signature of JE/AE/EE

[Signature]
20/4/22
RR

[Signature]
19/4/22
Signature
(Name of Inspection)

Balthi — Togio
Schedule XLV-Form No. 134

Thanjharapur

DIVISION

Madhepur

SUB-DIVISION

3011

MEASUREMENT BOOK

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
① Providing and filling brick bats					
99.63 m ² @ 7.4 BP-①					
2004.96/m ² — AS					199754.17
					RS 199754.17
Add 12% GST @ AS					23970.50
Add 1% L-COSS @ AS					1997.54
Add 10% S.Fee @ AS					2281.82
					RS 236004.03
					Say RS 236004.00
AS 8/5/2018					MS 08/05/2022
					S.E