

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- L035 - Bheja Langra Chowk to Jharua (ODR 40)

A. For Road

1. Damage Location Chainage :- 1300 to 1400, 1700 to 1850 & 1900 to 2150
2. Damage Length :- ~~0.157 Km~~ 67.60m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick's Bat's
 - ii. Equipment's/Tools being used in Restoration works:- Tractor & JCB
 - iii. Procedure taken up in Restoration works:- 116.06 cum
 - iv. Restored Length:- ~~0.157 Km~~ 67.60m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-


C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE


26/04/22
JE


23/4/22
RR


29/4/22
Signature
(Name of Inspection)

Schedule XLV-Form No. 134

L035 - Bheja Langra Chowk to Jharwa (ODR40)

Jhanjharpur

DIVISION

Madhepur

SUB-DIVISION

2088

MEASUREMENT BOOK

