

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- *Kharik Madhepur*

Name of Road :- *Kharik Main Road to Paswan tola*

A. For Road

1. Damage Location Chainage :-
2. Damage Length :- *43.00 m*
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- *Bricks Bats*
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:- *65.25 m*
 - iv. Restored Length:-

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

[Signature]
01/05/22
JE

Signature of JE/AE/EE

[Signature]
20/4/22
EE

[Signature]

[Signature]
11/11/22

Signature
(Name of Inspection)

Schedule XLV-Form No. 134

Kharik main Road To Pasudan To/a

Ikan Jharpur _____ DIVISION

Madhepur _____ SUB-DIVISION

3027

MEASUREMENT BOOK

[illegible][illegible]