

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhnau

Name of Road :- Madhubani Tilantargat Lakhnau ke Harbhanga Bajrangbali
Asthan Se Makkeori Mahadelit Tola

A. For Road

1. Damage Location Chainage :- 300, 350 m
2. Damage Length :- 25.0 m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bats
 - ii. Equipment's/Tools being used in Restoration works:- Tractor
 - iii. Procedure taken up in Restoration works:- 2.70 m³
 - iv. Restored Length:- 25.0 m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

Signature
(Name of Inspection)

HARBHANGA BAJRANGBALI STHAN SEMAKKARI MAHPALIT TOL
F. D. R. 2021/2022 (P.D.R.)

Schedule XLV Form No. 134.

DIVISION

LAKHANAU

SUB-DIVISION

Measurement Book

2075

Scanned with CamScanner