

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhnagar

Name of Road :- Dip Salhesi Sthan to Balwa tal

A. For Road


1. Damage Location Chainage :- 0 to 700 m
2. Damage Length :- 99 m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Bricks Bats
 - ii. Equipment's/Tools being used in Restoration works:- tractor
 - iii. Procedure taken up in Restoration works:- ~~20/10~~ 4.875 m³
 - iv. Restored Length:-

B. For Bridge


1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-


Signature of JE/AE/EE


3036
23/4/22
RR


Signature
(Name of Inspection)

DIP SALHESH STHAN TO BALWATOL (F.D.R.)
F.D.R. - 2021-2022

Schedule XLV Form No. 134.

_____ **DIVISION**

LAKHANAU. _____ **SUB-DIVISION**

Measurement Book

2077

(These four lines should be repeated at the commencement of the measurement relating to each work)

[illegible]

Scanned with CamScanner