

Estimate for Restoration work of Road from SH to Chahuta for the year 2021-2022 in Bisfi lock

Length-2.56 KM

NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
Ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amount
0 to 1 Km	1	1.50	2.75	0.15	0.62			
	1	1.00	1.00	0.15	0.15			
	1	3.00	0.90	0.15	0.41			
	1	7.00	2.00	0.15	2.10			
	1	7.00	3.00	0.15	3.15			
	1	6.00	3.00	0.15	2.70			
	1	1.00	2.00	0.15	0.30			
	1	1.00	1.00	0.15	0.15			
	1	3.50	3.50	0.15	1.84			
	1	2.50	3.50	0.15	1.31			
	1	10.50	1.50	0.15	2.36			
	1	16.50	3.50	0.15	8.66			
	1	7.00	1.50	0.15	1.58			
	1	2.50	1.50	0.15	0.56			
2 to 2.5 Km	1	4.70	3.00	0.15	2.12			
	1	18.00 15	2.75	0.30 0.25	14.85		10.3125 M ³	
	1	7.50	1.50	0.15	1.69			
	1	3.50	3.00	0.60 0.45	6.30		4.725 M ³	
	1	1.50	1.00	0.15	0.23			
	1	10.00	1.00	0.15	1.50			
	1	5.00	1.00	0.15	0.75			

1	5.00	1.50	0.15	1.13			
1	7.00	2.75	0.15	2.89			
				57.33	Cum	1939.93	99382.61
							111209

$L = 129.20 \text{ Mtr.}$

Add 12% GST

Add 1% L/Cess

Add Signorage Fee(57.33x1032X10%)

Total

51.23 M³

51.23

=Rs

=Rs

=Rs

=Rs

119262.13345

994 = 1112

5287 = 5916

131582

00. 117590.00

Bhaskar
JE
4/12/21

RWD
Bisfi

Sanjay
AE
4/12/21

AE
RWD
Bisfi

Sanjay
EE
4/12/21

EE
RWD
Benipatti

Damaged length = 129.20 Mtr.

Restored Qty. = 51.23 M³

Verified & found correct as per site condition

Sanjay
19/02/22
E.C

Kr. Kumar

AZ

Name of Road:- SH To chahuta

Post-facto T/S awarded for Rs. 117590.00
(Rs one Lac seventeen thousand five hundred
ninety only.)

Reference Letter no. 233 dated 21/2/22
of E.E. Darbhanga-2


Superintending Engineer
RWD Works Circle, Darbhanga

21/2/22

Rem

24

ature

24

(10)

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :-
Name of Block/PIU :- Bis-fi (Inspected RWD(W) Div. Benipatti)
Name of Road :- SH To Chahuda
For Road :-

1. Damage Location/ Chainage :- 0-to 01 km.
2. Damage Length :- 129.20 Metre
3. Nature of Damage :- Pot patch
4. Details of Restoration Works :-
 - i. Material being used in Restoration Works - Tractor Brick Bricks
 - ii. Equipment's/ Tools being used in Restoration Works Tractor & Roller
 - iii. Procedure taken up in Restoration Works - Section-wise compaction
 - iv. Restored Length - 129.20 Metre

Remarks :- Work found satisfactory. *underway*

Signature of JE/AE

K. V. ...
19/02/2022

Signature of E.E

19/02/22

JE
19/02/22