

Estimate for Restoration work of Road from Parsauni to Raghopur for the year 2021-2022 in
 Sfi Block
 Length-4.450 KM

NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
Ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amount
0 to 1 Km	1	2.00	1.50	0.15	0.45			
	1	2.00	2.00	0.15	0.60			
	1	5.00	4.00	0.15	3.00			
	2	4.00	1.50	0.15	1.80			
	1	1.00	1.00	0.15	0.15			
1 to 2 Km	1	6.00	2.00	0.15	1.80			
	1	5.00	1.50	0.15	1.13			
	1	10.00	1.50	0.15	2.25			
	3	1.00	1.00	0.15	0.45			
	1	4.00	1.50	0.15	0.90			
2 to 3 Km	1	20.00	3.00	0.15	9.00			
	1	7.00	2.00	0.15	2.10			
	1	10.00	2.50	0.25	6.25			
	1	1.50	1.50	0.15	0.34			
	3	2.50	2.50	0.15	2.81			
3 to 4 Km	1	2.00	2.00	0.15	0.60			
	1	5.00	3.00	0.30 0.25	4.50 3.75 m ³			
	1	2.50	3.00	0.15	1.13			
	1	8.00	2.50	0.15	3.00			
	1	2.00	3.00	0.15	0.90			
	1	5.00	3.00	0.15	2.25			
					45.40	Cum	1939.93	88073

14.75 m³
 m

86812.00

Add 12% GST =Rs
 Add 1% L/Cess =Rs
 Add Signorage Fee(45.40x1032X10%) =Rs
 Total 17.75 =Rs

BF- 86812 =

1056910412 =

821 268 =

4685 4618 =

104208

PO, PS- 102715

Dhanya
 4/12/21
 JE
 RWD
 Bisfi

Jaunt
 4/12/21
 AE
 RWD
 Bisfi

My
 4/12/21
 EE
 RWD
 Benipatti

Damaged length = 105.50 mtr.

Restored Qty. = 44.75 M³

verified and found correct as per
 site condition

Kr. un

Signature
 10/02/22
 EE

A2

Name of Road:- Parsauni to Raghapur

Post-facto T/S accorded for Rs. 102715.00
(Rs. one lac two thousand seven hundred
fifteen only)

Reference letter no. 233 dated 21/2/22
of Darbhanga - 2


Superintending Engineer
RWD Works Circle, Darbhanga
21/2/22

actor.
and
ely.
1'
12

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :-
Name of Block / PIU :- Bisti (RWD(W) Div- Benipatti)
Name of Road :- Parsauni To Raghapur
For Road :- 0 to 04 km

1. Damage Location/ Chainage :-

2. Damage Length :- 105.50 Metre

3. Nature of Damage :- Pot patch.

4. Details of Restoration Works :-

i. Material being used in Restoration Works - Brick Bats

ii. Equipment's/ Tools being used in Restoration Works - Tractor & Roller

iii. Procedure taken up in Restoration Works - Section wise compaction

iv. Restored Length - 105.50 Metre

Remarks :- Work found satisfactory. *mm*
19/02/22
Signature of E.E

Signature of JE/AE

W. m
19/02/22
JE