

Schedule XLV From N.134.

P.W.D.

प्राप्त - ०१२११२

NABARD

Thakchand shing sirday mmsy to Ravi Mohan

DIVISION

Contractor Name: Manoj Kumar Singh,

SUB DIVISION

Mohampur, Deeghar

## MEASUREMENT BOOK

M.B. No-1571

CND

8-3-22

Sch. XLV- Form No. 134

| Particulars                              | Details of actual measurement |    |    |    | Contents or area |
|------------------------------------------|-------------------------------|----|----|----|------------------|
|                                          | No.                           | L. | B. | D. |                  |
| <u>III<sup>rd</sup> year Maintenance</u> |                               |    |    |    |                  |
| M/A - Demol <sup>n</sup> of road from    |                               |    |    |    |                  |
| Thakshand Sima Siradag to                |                               |    |    |    |                  |
| Badi Mahari.                             |                               |    |    |    |                  |
| Agency - Hamojka Singh                   |                               |    |    |    |                  |
| Ag. No - 943B2/17-18                     |                               |    |    |    |                  |
| Date of Actual comp - 20/1/19            |                               |    |    |    |                  |
| Date of measurement -                    |                               |    |    |    |                  |

① Restoration of road

|    |       |       |      |                      |
|----|-------|-------|------|----------------------|
| 2x | 11.0x | 1.10x | 0.30 | 7.26 m <sup>3</sup>  |
| 3x | 15.0x | 1.0x  | 0.30 | 13.50 "              |
| 6x | 13.0x | 1.0x  | 0.30 | 23.40 "              |
| 2x | 22.0x | 1.0x  | 0.30 | 13.20 "              |
| 5x | 13.0x | 1.0x  | 0.30 | 20.47 "              |
| 4x | 6.0x  | 1.10x | 0.30 | 13.86 "              |
|    |       |       |      | 91.69 m <sup>3</sup> |

② Making up of berms /  
shoulder

|       |       |      |   |                       |
|-------|-------|------|---|-----------------------|
| 2x2x  | 9.0x  | 1.10 | = | 39.60 m <sup>2</sup>  |
| 2x10x | 8.0x  | 1.10 | = | 176.00 "              |
| 2x6x  | 3.0x  | 1.10 | = | 39.60 "               |
| 2x8x  | 15.0x | 1.0  | = | 240.00 "              |
| 2x2x  | 4.0x  | 1.0  | = | 16.00 "               |
|       |       |      |   | 511.20 m <sup>2</sup> |

③ Patch repair - do

|    |      |      |   |                      |
|----|------|------|---|----------------------|
| 2x | 4.0x | 1.50 | = | 12.00 m <sup>2</sup> |
| 2x | 3.0x | 1.0  | = | 6.00 "               |
| 4x | 3.0x | 1.50 | = | 18.00 "              |

(Continuation)

