INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs: - EE, RWD, Kishayouy-2
Name of Block/Road: - Dighalbank Tulsza to Bibigan
A. For Road
1. Damage Location/Chainage:- 6-1 Km
2. Damage Length: - Gama 30m
3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
Gii) Only Flank Damage :-
whether traffic fully/Partially obstructed :- fully obstructed
4. Details of Restoration:
(i) Material Being Used in Restoration: - & Local Sand, Bamboo, Sand Bay
(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB
(iii) Restored Length In open Area:-
In habitation Area:-
(iv) If Restoration work done in habitation Area give Reason :-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage :-
(2) No. of Span Damage :-
(3) Length of Span :-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-
(5) Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works :-
(iii) Restored Length :-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):-

Signature of Inspector, vision (Official Scalar & Dr. 1)

4. Jumes