

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E (W.D) Bikharna (Batalga)

Name of Block/Road :- Gurhenwa - Balua Tola Guabari

A. For Road

Damage Location/Chainage :-

Damage Length :- 0.065 km

Nature of Damage (Length Wise) (i) Breach :- 0.065 km
(ii) Crust Damage :-
(iii) Only Flank Damage :-

Whether traffic fully/Partially obstructed :- 0.065 km

Details of Restoration :-

i) Material Being Used in Restoration :- Bricks / Bats / Cement / Mortar

ii) Equipment/Tools Being Used in Restoration Works :- JCB / Trencher / Trolley / Wheelbarrow

iii) Restored Length In open Area :- 0.065 km
In habitation Area :-

iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1) Damage Location/Chainage :-

2) No. of Span Damage :-

3) Length of Span :-

4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-

5) Details of Restoration :-

i) Material Being Used in Restoration :-

ii) Equipment/Tools Being Used in Restoration Works :-

iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

29.11.24
A.E. Raxaul

Signature of Inspector
(Official Seal)
29.11.24
EE Dhaka