INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- E.E RWID (W) Sikharna (18holes)
Name of Block/Road: Bhaka Ghormahan Road of Kasws laykhor Paswen.
Wonigh and Yodov Tola W. 40-1,2
. Damage Location/Chainage :-
Daniel Landh
Damage Length:- 0.115 km,
Nature of Damage (Length Wise) (i) Breach:- 0.115 WM
(ii) Crust Damage :-
hether traffic fully/Partially obstructed:
Details of Restoration:
Brick Iso America
i) Equipment/Tools Being Used in Restoration Works: - Jes Trock Trolly Roll
ii) Restored Length In open Area:-
In habitation Area :-
v) If Restoration work done in habitation Area give Reason:-
For Bridge (Size of Bridge/Culvert)
1) Damage Location/Chainage:-
2) No. of Span Damage :-
3) Length of Span:-
4) Nature of Damage (Pier/Abuttment/
Ving Wall/Approach Road Damage):-
5) Details of Restoration:-
) Material Being Used in Restoration:-
i) Equipment/Tools Being Used in Restoration Works :-
ii) Restored Length :-
overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Cabillater
The state of the s
Josapar .
Signature of Inspector 1 mg Paral
(Official Seal)
19.11.24.
11. E. Raxan.