

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-

Elaurav Kumar

Name of Block/Road :-

(Terhagachh) Lo44 Bhag Kalleto to Rishidev to la Khurkhuria

A. For Road

1. Damage Location/Chainage :- 500 m

2. Damage Length :- 320 m

3. Nature of Damage (Length Wise)

(i) Breach :- L. side 110m R. side 210m

(ii) Crust Damage :- Crust damage

(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brickbats, Ecbaq, bamboo

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length

In open Area :- 320m

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

N/A

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)