INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- E.E. RW	D Barson	1
Name of Block Road :- Cadas	Malikpur Ao Barol Mg Kaverya	15
For Road		de
Damage Location/Chainage :-		
namage Length: 0.043 &	leus	-
Nature of Damage (Length Wise)	(i) Breach: 0.043 Km	
, Natur	(ii) Crust Damage :-	4
	(iii) Only Flank Damage :-	4
whether traffic fully/Partialiy obstru	acted: fully abstraction.	-
Details of Restoration:		\dashv
i) Material Being Used in Restorati	ion: grick bab, followsh	4
(ii) Equipment/Tools Being Used in	Restoration Works:	
(iii) Restored Length	In open Area:- 0.043 km	- Carefrance
	In habitation Area:-	SEASON SEASON
(iv) If Restoration work done in hal	bitation Area give Reason:-	A Section 1 is not find
B. For Bridge (Size of Bridge/C	Culvert)	
(1) Damage Location/Chainage:-		Sept. Are Sept.
(2) No. of Span Damage:-		-
(3) Length of Span :-		
(4) Nature of Damage (Pier/Abuttn	nent/	
Wing Wall/Approach Road Damag	ge) :-	-
(5) Details of Restoration:		
(i) Material Being Used in Restorat	tion:-	
(ii) Equipment/Tools Being Used i	n Restoration Works :-	_
(iii) Restored Length :-		
	104-11	_
Overall Grade of Restoration we	ork (Satisfactory/Unsatisfactory):-	_
	ork (Satisfactory, Chause	
	13 [II]	
	Signature of Inspector	
	(Official Seal)	