

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-		E.E. RWD (W) Sikhana Idhaka	
Name of Block/Road :-		Purnagya Vijai Path to Vijai Khark word No-06 (Anseri to 19)	
A. For Road			
Damage Location/Chainage :-			
Damage Length :- 0.100 Km.			
Nature of Damage (Length Wise)	(i) Breach :-	y	
	(ii) Crust Damage :-	y	
	(iii) Only Flank Damage :-	y	
Whether traffic fully/Partially obstructed :- y			
Details of Restoration :- y			
Material Being Used in Restoration :- y			
i) Equipment/Tools Being Used in Restoration Works :- y			
ii) Restored Length	In open Area :-	y	
	In habitation Area :-	y	
v) If Restoration work done in habitation Area give Reason :- y			
B. For Bridge (Size of Bridge/Culvert)			
1) Damage Location/Chainage :-			
2) No. of Span Damage :- y			
3) Length of Span :- 0.100 km (Approach Road)			
4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :- Approach Road Damaged			
5) Details of Restoration :- Approach Road Damaged			
Material Being Used in Restoration :- Jca / Trector / Trolley / Roller Brick Bats			
ii) Equipment/Tools Being Used in Restoration Works :- Jca / Trector / Roller			
iii) Restored Length :- 0.100 km			
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory			

Signature of Inspector
(Official Seal)

30/11/24
E.E. RWD, Raxaul.

30/11/24
E.E. Idhaka

30.11.24
A.E. Raxaul.