

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE R.W.D Basni
Name of Block/Road :- Kalwa. Pabal lila Shikwana to Pussy. P.W.

A. For Road

1. Damage Location/Chainage :-

2. Damage Length :- 0.124 km

3. Nature of Damage (Length Wise) (i) Breach :- 0.124 km
(ii) Crust Damage :-
(iii) Only Flank Damage :-

Whether traffic fully/Partially obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Boulder Bels

(ii) Equipment/Tools Being Used in Restoration Works :- JCB Tractor.

(iii) Restored Length

In open Area :-

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)