INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RV	UD Barsoni wa PMUSY Road to Muchambila UPR
Name of Block/Road :- Kalu	wa PMUSSY Road to Muchambula UPR
A. For Road	
1. Damage Location/Chainage:-	
2. Damage Length :-	0-030 Km
3. Nature of Damage (Length Wise)	(i) Breach:- 0 - 030 cm
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstru	cted: fully of thinks
4. Details of Restoration:-	
(i) Material Being Used in Restorati	on: Pombes Dels
(ii) Equipment/Tools Being Used in	Restoration Works: 5 CB Truestis
(iii) Restored Length	In open Area:-
	In habitation Area:-
(iv) If Restoration work done in hab	sitation Area give Reason :-
B. For Bridge (Size of Bridge/C	
(1) Damage Location/Chainage:-	
(2) No. of Span Damage:-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttm Wing Wall/Approach Road Damage	ent/ e):-
5) Details of Restoration:-	
Moterial Being Used in Restorati	ion:-
ii) Equipment/Tools Being Used in	Restoration Works :-
iii) Restored Length :-	
	my victory) :-
U Grade of Restoration Wo	rk (Satisfactory/Unsatisfactory) :-
overall Grade of Restoration	25/11/10)4
	Signature of Inspector
	(Official Seal)