INSPECTION REPORT FOR MOTORABLE WORK

of PIUs: E.E-RWD	Bressi
Name of Block Road :- La day	Bassoi / Jasq Bellan agon to MM654 Now
Name	19 6 man 4900) to HM654 1000
A. For Road Damage Location/Chainage :-	
Damage Location Chanage	
nomage Length: 0.06	264
Nature of Damage (Length Wise)	(1) Breach: 0.062 km
	(II) Crust Damage :-
	(iii) Only Flank Damage :-
hether traffic fully/Partially obstruc	cted: fully abstraction.
Details of Restoration:	
Material Being Used in Restoration	on: - Bricks bat, fobbish
ii) Equipment/Tools Being Used in	Restoration Works:- Jeb, Bactor.
(iii) Restored Length	In open Area:- 0.045-4
	In habitation Area:-
iv) If Restoration work done in habi	tation Area give Reason:-
B. For Bridge (Size of Bridge/C	ulvert)
1) Damage Location/Chainage:-	
2) No. of Span Damage:-	
3) Length of Span:-	
Pier/Abuttm	ent/
Wing Wall/Approach Road Damage	;):-
(5) Details of Restoration:	
Doing Used in Restorati	on :-
(ii) Equipment/Tools Being Used in	Restoration Works:-
ii) Equipment/1001s Being Code	
iii) Restored Length:-	
	rk (Satisfactory/Unsatisfactory):-
Overall Grade of Restoration wo	rk (Satisfactory, Ondania
orden Glade of Ites	25/11/701/
	Signature of Inspector (Official Seal)
	Official Seal)
	(Olliotal Star)