## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- E.E. RWD Basson
Name of Block/Road: - Block/ Por-Keday to Mainggar Road.
A. For Road
1. Damage Location/Chainage:-
2. Damage Length: 0.095 last
3. Nature of Damage (Length Wise) (i) Breach:- 0.0 95 tow
(ii) Crust Damage :-
(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed: fully abstructed.
4. Details of Restoration:-
(i) Material Being Used in Restoration: onice both forbish
(ii) Equipment/Tools Being Used in Restoration Works: JeB, Tractor
(iii) Restored Length In open Area:- 0-095-M
In habitation Area:-
(iv) If Restoration work done in habitation Area give Reason:-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage:-
(2) No. of Span Damage:-
(3) Length of Span:-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-
(5) Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works:-
(iii) Restored Length:-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):-
Overall Grade of Restolution
Geneture of Inspector
> Signature of inspector
(Official Seal)