INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD, Work	Divisim, DEHRI
Name of Block Road :- NAU	HATTA / DEHRI YADUNATHPUR ROADTO NAWA
A. For Road	
1. Damage Location/Chainage :-	2.150 KM
Damage Length :-	7.50 M
Nature of Damage (Length Wise)	(i) Breach :- 7.50 M
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partialiy obstruc	sted :- FULLY OBSTRUCTED
4. Details of Restoration :- Hu	me pipe (1000mm dia) provided.
(i) Material Being Used in Restoration	on: Granular Material (918 Type)
(ii) Equipment/Tools Being Used in	Restoration Works: 3CB, Treetor Trolley.
(iii) Restored Length	In open Area:- 7.50 M
	In habitation Area:-
(iv) If Restoration work done in habi	tation Area give Reason:-
B. For Bridge (Size of Bridge/C	ulvert)
(1) Damage Location/Chainage:-	-
(2) No. of Span Damage:-	-
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttme Wing Wall/Approach Road Damage	ent/ e):-
(5) Details of Restoration:-	
(i) Material Being Used in Restorati	on:-
(ii) Equipment/Tools Being Used in	Restoration Works:-
(iii) Restored Length :-	

Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- 54TISFACTOR

Signature of Inspector (Official Scall) भयंता ग्रामीण कार्य विभाग कार्य प्रमण्डल, भभुआ