

1st year maintenance

Record Entry

49

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Mohan Chandpur Banath to Azampur shankar Banath under (W.B.)					
N/A - m/s Holden Company. Agg. no - 4/MBD/2020-21 Actual comp dt - 18/09/2022. (measurement)					
① Restoration of Reinforce.					
	2	30	1.20	0.30	$= 21.6m^3$
	3	11.0	1.0	0.30	$= 9.9m^3$
					$\Sigma = 31.5m^3$
(2/3) maint. of Gutter slough					
	2	30	1.20		$= 22.0m^2$
	3	11.0	1.0		$= 33.0m^2$
	3	17.0	1.80		$= 91.8m^2$
					$\Sigma = 196.8m^2$
(3/3) maint. of roof holes to report					
	6	2.5	1.0		$= 15.0m^2$
	3	60	0.30		$= 5.58m^2$
					$\Sigma = 20.58m^2$
(4/4) maint. of Bifurmer Surface on S - side					
	3	3.5	0.9		$= 9.45m^2$
	1	1.0	0.8		$= 0.8m^2$

Continuation

$\Sigma = 10.25m^2$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(56) maint. of culvert.				$Q =$	2 Nos.
(67) maint. of Road sign				$Q =$	0.163 km
(7) Maint. of round km stem				$Q =$	0.195 km
(8/10) cutting of shrubs trees				$Q =$	2 Nos
(11) white washing of parapet wall of culvert				$Q =$	9 ml
20/9/17 20/9/22 20/9/22 20/9/22					

Abstract of Cost

(1) Restoration of Rain cuts.					
Qty vide works pr. 49					
$Q = 31.5 m^3 @ 410.20/m^3$					12921.00
(2) maint. of Earthen stretch					
Qty vide works pr. 49					
$Q = 196.8 m^3 @ 63.24/m^3$					12445.00
(3) maint. of Pot hole					
Qty vide works pr. 49					
$Q = 20.58 m^3 @ 360.01/m^3$					7384.00
(4) maint. of bitumen surface.					
Qty vide works pr. 49					
$Q = 10.25 m^2 @ 248.59/m^2$					2548.00

Continuation

= 35,298.00

Continuation