

IMMERSY, T03 to organobacch (Chaparrack
Kumar-Pale)

Schedule XLV-Form No. 134

104. below

Ag. No. 44800/19-00

Ag. Value - 59.12293.2.

Rev. (w) oliv. Shenghau **DIVISION**

Area **SUB-DIVISION**

Agency - vils moa shanti court.

Measurement Book

1154

3rd Year Maintenance bill

66

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - To Mansadih					
Agency - MAA Shakti Construction					
Agreement No. - 77850/19-20					
Item-①	Restoration of Raincups/ Beams with solid				
	10	4.80	1.10	0.30	15.84M ²
	8	3.10	1.15	0.25	7.13M ²
	9	5.20	1.20	0.30	16.84M ²
	8	5.10	1.15	0.30	14.07M ²
	3	2.10	0.90	0.25	1.41M ²
					55.29M ²
proposed 2nd floor					
Item-②	Making up of Beams/ Shoulder				
	10	4.60	1.20	=	55.20M ²
	9	4.10	1.10	=	40.59M ²
	8	3.90	1.15	=	35.88M ²
	10	5.10	1.20	=	61.20M ²
	9	4.30	1.15	=	44.50M ²
	10	4.80	1.10	=	52.80M ²
	10	2.10	1.15	=	24.15M ²
					314.32M ²
Item-③	Repair of pot holes filled with 75mm 4.8M				
	10	1.30	0.80	=	10.4M ²
	9	1.10	0.90	=	8.91M ²
	11	1.40	1.10	=	16.94M ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	9X	1.30X	0.800	=	9.36 m ²
	10X	0.950X	0.800	=	7.60 m ²
	5X	1.10X	0.500	=	2.75 m ²
					55.96 m ²
item-④	patch repair over Rift zones surface				
	10X	1.80X	1.10	=	19.80 m ²
	9X	1.10X	0.900	=	8.91 m ²
	11X	1.20X	1.15	=	15.18 m ²
	9X	0.900X	0.700	=	5.67 m ²
	10X	0.800X	0.500	=	4.00 m ²
	3X	0.800X	0.400	=	0.72 m ²
					54.28 m ²
item-⑤	Maintenance of C.P works (H.P culvert)				
					— 4 Hb
item-⑥	Maintenance of Road				
					88th — 0.15 km
item-⑦	Maintenance of road and km slope — 0.18 km				
item-⑧	cutting of branches of tree and stumps — 2 Hb				
item-⑨	white wash of paved wall of aqueduct				
	8X	6.00X	0.400	=	19.20 m ²
	2X	8X	6.00X	0.600	57.60 m ²
	16X	0.400X	0.600	=	7.84 m ²
					80.64 m ²

Continuation

A.1012m
22/01/23
a

ABSTRACT OF GST

68

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/15.1A) Restoration of Rainvues					
V.T.M.B.P.No - (66)					
item (1) — 55.29 m ²					
Q 371.85/m ² — 20532.50					
(2/15.2A) Maching up of Beras/					
shoulder					
V.T.M.B.P.No - (66)					
item (2) — 314.32 m ²					
Q 55.95/m ² — 17586.00					
(3/15.5) Repair of pot holes					
filled with trash					
V.T.M.B.P.No - (66)					

item (3) — 55.90 m ²					
Q 161.33/m ² — 9028.00					
(4/15.3A) Patch repair over					
Bituminous surface					
V.T.M.B.P.No - (67)					
item (4) — 54.28 m ²					
Q 161.33/m ² — 8787.00					
(5/15.7A) Maintenance of cut					
work (H.P. culvert)					
V.T.M.B.P.No - (67)					
item (5) — 4 m					
Q 1109.67/m ² — 4439.00					
(6/15.9) Maintenance of Road					
sign					
V.T.M.B.P.No - (67)					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	item (6)	—	0.15	km	
	Q 1066	51/100	—	160.00	
(7/15-11)	Maintenance of				
	road, 10.17 slope				
	V.T.M.B.P.H. (62)				
	item (7)	—	0.18	km	
	Q 728	78/100	—	131.51	
(8/15-12)	Cutting of branches				
	of tree and plunks				
	V.T.M.B.P.H. (62)				
	item (8)	—	2.16		
	Q 105	39/100	—	211.2	
(9/15-13)	White washing of				
	porcupine wall				
	V.T.M.B.P.H. (62)				
	item (9)	—	80.64	km	
	Q 1634	1/100	—	1318.00	
				62162.00	
	(or 10% below)			6216.00	
				55946.00	
A-104207 27/01/23 DL					

Continuation